

Jericho Underhill Water

P.O. Box 174

100300

Underhill, VT 05489

Atten: Nancy Benson

PROJECT: WSID 5096 DBP

WORK ORDER: **2609-31533**

DATE RECEIVED: September 01, 2026

DATE REPORTED: September 17, 2026

SAMPLER: Ryan Cotnoir

VT0005096

Laboratory Report

Enclosed please find the results of the analyses performed for the samples referenced on the attached chain of custody. All required method quality control elements including instrument calibration were performed in accordance with method requirements and determined to be acceptable unless otherwise noted.

The column labeled Lab/Tech in the accompanying report denotes the laboratory facility where the testing was performed and the technician who conducted the assay. A "W" designates the Williston, VT lab under NELAC certification ELAP 11263; "R" designates the Lebanon, NH facility under certification NH 2037 and "N" the Plattsburgh, NY lab under certification ELAP 11892. "Sub" indicates the testing was performed by a subcontracted laboratory. The accreditation status of the subcontracted lab is referenced in the corresponding NELAC and Qual fields. The Williston, VT facility is also ISO/IEC 17025:2017 accredited for Total Coliform and E coli by SM9223B.

The NELAC column also denotes the accreditation status of each laboratory for each reported parameter. "A" indicates the referenced laboratory is NELAC accredited for the parameter reported. "N" indicates the laboratory is not accredited. "U" indicates that NELAC does not offer accreditation for that parameter in that specific matrix. Test results denoted with an "A" meet all National Environmental Laboratory Accreditation Program requirements except where denoted by pertinent data qualifiers. Test results are representative of the samples as they were received at the laboratory.

Endyne, Inc. warrants, to the best of its knowledge and belief, the accuracy of the analytical test results contained in this report, but makes no other warranty, expressed or implied, especially no warranties of merchantability or fitness for a particular purpose.

Reviewed by:



Harry B. Locker, Ph.D.
Laboratory Director

Laboratory Report

DATE REPORTED: 09/17/2026

CLIENT: Jericho Underhill Water
PROJECT: WSID 5096 DBP

WORK ORDER: 2609-31533
DATE RECEIVED: 09/01/2026

001 Site: United Church 7 Park Street

Date Sampled: 8/31/26 Time: 15:10

Facility ID: DS001 Smp Pt: HA001 Categ: GE Smp Type: RT Compl Ind: Y Repl Ind: N

Parameter	Result	Units	Method	Analysis Date/Time	Lab/Tech	NELAC	Qual.
HALOACETIC ACIDS							
552 Extraction	Complete		EPA 552.2	9/4/26	W GLB	A	
Monochloroacetic Acid	< 5.0	ug/L	EPA 552.2	9/12/26	W DPD	A	
Monobromoacetic Acid	< 3.0	ug/L	EPA 552.2	9/12/26	W DPD	A	
Dichloroacetic Acid	< 3.0	ug/L	EPA 552.2	9/12/26	W DPD	A	
Trichloroacetic Acid	< 3.0	ug/L	EPA 552.2	9/12/26	W DPD	A	
Dibromoacetic Acid	< 3.0	ug/L	EPA 552.2	9/12/26	W DPD	A	
Total Haloacetic Acids	< 17.0	ug/L	EPA 552.2	9/12/26	W DPD	A	
Surrogate-DBPA	96	%	EPA 552.2	9/12/26	W DPD	A	

002 Site: 38 Poker Hill Road

Date Sampled: 8/31/26 Time: 15:20

Facility ID: DS001 Smp Pt: TH001 Categ: GE Smp Type: RT Compl Ind: Y Repl Ind: N

Parameter	Result	Units	Method	Analysis Date/Time	Lab/Tech	NELAC	Qual.
TRIHALOMETHANES							
Chloroform	1.0	ug/L	EPA 524.2	9/9/26	W TRP	A	
Bromodichloromethane	< 0.5	ug/L	EPA 524.2	9/9/26	W TRP	A	
Dibromochloromethane	< 0.5	ug/L	EPA 524.2	9/9/26	W TRP	A	
Bromoform	< 0.5	ug/L	EPA 524.2	9/9/26	W TRP	A	
Total Trihalomethanes	1.0	ug/L	EPA 524.2	9/9/26	W TRP	A	
Surr. 1 (4-Bromofluorobenzene)	84	%	EPA 524.2	9/9/26	W TRP	A	
Surr. 2 (1,2-Dichlorobenzene d4)	84	%	EPA 524.2	9/9/26	W TRP	A	

Endyne will submit this data electronically to the State of VT Water Supply Division in accordance with their policy and standards.

Endyne Inc. COC

2609-31533

WSID 5096 DBP

Prepared: 8/31/26

Bill to:

Nancy Benson
Jericho Underhill Water
P.O. Box 174
Underhill VT 05489
Ph: 802-899-3017

Report to:

Nancy Benson
Jericho Underhill Water
P.O. Box 174
Underhill VT 05489
mmaheux@juwater.org;clerk@juwal

Cust #

VT

DBP



Jericho Underhill Water
WSID 5096 DBP

Facility ID: DS001 Smp Pt: HA001 Categ: GE Smp Type: RT Repl Ind: N Compl Ind: Y/N

United Church 7 Park Street

Sampled Date/Time:

08/31/26 @ 3:10 PM

Haloacetic Acids

3 - 60 ml Amber Vials

<6C, NH4Cl

Facility ID: DS001 Smp Pt: TH001 Categ: GE Smp Type: RT Repl Ind: N Compl Ind: Y/N

38 Poker Hill Road

Sampled Date/Time:

08/31/26 @ 3:30 PM

VOC THMs

2 - 40 mL Amber Vials

<6C, Thiosulfate

Sampler::

Ryan Catnoir

Relinquished by:

Ryan Catnoir

09/01/26

Date Time

Accepted by:

Date Time

Relinquished by:

Received by:

Date Time

Sites/Parameters correct as listed. Client Initials _____

Client Authorization to use Subcontract lab Client Initials _____

Sample origin: VT ☐ NH ☐ NY ☐ Other ☐

Special reporting instructions: (PO#) _____

Requested Turnaround Time: Routine: Rush Due Date _____

Delivered

Temp C: 0.8

Comment:

One or more sample bottles in this project must be kept refrigerated or on ice until delivery at the laboratory.

Initial here allow Endyne to proceed with analysis if the temperature preservation requirements are not satisfied. _____ Initial

Samples were received in the lab on ice. (Y)N



ENDYNE
ENVIRONMENTAL LABORATORY SERVICES

160 James Brown Dr.
Williston, VT 05495
Ph 802-879-4333

56 Etna Road
Lebanon, NH 03766
Ph 603-678-4891

315 New York Rd.
Plattsburgh, NY 12903
Ph 518-563-1720