



Laboratory Services

160 James Brown Drive  
Williston, Vermont 05495  
(802) 879-4333  
FAX 879-7103

LABORATORY REPORT

Jericho Underhill Water  
PO Box 236  
Underhill, VT 05489  
Attn: Marc Maheux

PROJECT: WSID #5096  
ORDER ID: 35120  
RECEIVE DATE: February 2, 2005  
REPORT DATE: February 4, 2005

Enclosed please find the results of the analyses performed for the samples referenced on the attached chain of custody. Different groups of analyses may be reported under separate cover.

All samples were prepared and analyzed by requirements outlined in the referenced methods and within the specified holding times.

All instrumentation was calibrated with the appropriate frequency and verified by the requirements outlined in the referenced methods.

Blank contamination was not observed at levels affecting the analytical results.

Analytical method precision and accuracy was monitored by laboratory control standards which include matrix spike, duplicate and quality control analyses. These standards were determined to be within established laboratory method acceptance limits, unless otherwise noted.


Reviewed by,

Harry B. Locker, Ph.D.  
Laboratory Director

enclosures







**LABORATORY REPORT**

CLIENT: Jericho Underhill Water

ORDER ID: 35120

PROJECT: WSID #5096

DATE RECEIVED: February 2, 2005

REPORT DATE: February 11, 2005

SAMPLER: MM

Ref. Number: 246124

Site: Control Building

Date Sampled: February 2, 2005

Time: 8:00 AM

<u>Parameter</u>	<u>Result</u>	<u>Unit</u>	<u>Method</u>	<u>Analysis Date</u>	<u>Analyst</u>
Nitrogen, Nitrate	< 0.020	mg/L	EPA 300.0	2/2/05	503

