

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800)220-3675 / (856)786-0327

<http://www.emsl.com> cinnaminsonradonlab@emsl.comEMSL Order #: **781700222**Customer ID: **MISC-ACCT**

Customer PO:

Attn: **Marc Mahuex****PO Box 174
Underhill, VT 05489**Project: **Jericho Underhill Water District**NELAC Certification #: **03036**

Phone:

Fax: **Not Available**Collected: **03/03/2017**Received: **03/07/2017**

Analytical Report

Sample Identification: 1 & 2**Lab Sample #: 781700222-0001****Date/Time Collected: 3/3/2017 05:15 AM**

<u>Test Parameter</u>	<u>Result</u> pCi/L	<u>Uncertainty</u> pCi/L	<u>SDWA DL</u> pCi/L	<u>Start Count Date/</u> <u>Time</u>	<u>Analyst</u>	<u>Status Count</u>	<u>Method</u>
Radium 226	0.14	0.10	0.56	3/15/17 3:17 PM	KP	First Count	EPA 903.0
Radium 228	0.44	0.25	0.50	3/14/17 1:12 PM	KP	First Count	EPA 904

* All analysis met quality control acceptance criteria unless otherwise specified.

* For Ra-228 batch, LCS and LCS Dup recovery percentage were higher than acceptance limits.

Report Date

03/31/2017

Report Revision

R0

Revision Comments

Initial Report

Kishor Paudel, Laboratory Manager

In no event shall EMSL be liable for indirect, special, consequential, or incidental damages, including, but not limited to, damages for loss of profit or goodwill regardless of the negligence (either sole or concurrent) of EMSL and whether EMSL has been informed of the possibility of such damages, arising out of or in connection with EMSL's services thereunder or the delivery, use, reliance upon or interpretation of test results by client or any third party. We accept no legal responsibility for the purposes for which the client uses the test results. In no event shall EMSL be liable to a client or any third party, whether based upon theories of tort, contract or any other legal or equitable theory, in excess of the amount paid to EMSL by client thereunder. The test results meets all NELAC requirements unless otherwise specified.